	Site Addendum for the		erfund Program perfund Site Assessment Activities (October 2	2012)
			nformation:	
Site Name:	West Lake Landfill, MOD0799009	32	City: Bridgeton	State: MO
EPA Project N	<b>1anager:</b> Dan Gravatt		START Project Manager: NA U.S. Geological Survey, Missouri Water Scien	ce Center
Approved By:	NA		<u> </u>	
Title:	USGS Project Manager John Schumacher	Date:	Prepared For: EPA Region 7 Superfund Div	vision
Approved By:				
Title:	USGS Center Director (Missouri Water) Mike Slifer	Date:	Prepared By:	
Approved By:	NA		John Schumacher U,S. Geological Survey Missouri Water S	Science Center
Title:	USGS QA Manager Myia Barr	Date:	1400 Independence Road Rolla, MO 65401	
Approved By:	Dan Gravatt		Date: August 27, 2013	
Title:	EPA Project Manager	Date:	START Contractor: NA	
Approved By:			START Project Number: NA	
	EPA Regional Quality Assurance Manager	Date:		
1.0 Project Ma	anagement:			
EPARegion 7	EPA Project Manager; EPA <u>Diane Harris</u> EPA RQAM		Schumacher S Project Manager	
Dan Gravatt is John Schumach Mike Slifer is th Paul Brenden is	ct/Task Organization the EPA Project Manager ter is the USGS Missouri Water Scienc te USGS Missouri Water Science Direc ts the USGS field team leader (project l tem Definition/Background:	ctor and responsible j	for all MWSC activities including projects	under this QAPP

Description: This addendum to the site-specific Quality Assurance Project Plan form has been prepared by the USGS. The site specific QAPP for Offsite sampling at the Westtlake Landfill was prepared as an addendum to the Generic Quality Assurance Project Plan for Superfund Integrated Assessment and Targeted Brownfields Assessment Program (Updated: October 2012), and contains site-specific data quality objectives for the sampling activities described herein.

The EPA desires to characterize naturally occurring background levels of radionuclides and other chemical constituents in the alluvial and bedrock aquifers surrounding the West Lake Landfill in Bridgeton / Earth City, MO, adjacent to the Missouri river. As part of this effort the EPA has requested assistance from the USGS. During June, 2013, the USGS conducted a search of USGS and MDNR and made a field reconnaissance on June 25, 2013. The field reconnaissance identified 7 private bedrock wells and 9 alluvial wells (with 5 additional alluvial wells possible) within 5-miles of the site that were potential candidates for sampling to establish background levels of chemical constituents. In July, 2013, the EPA sampled 6 alluvial wells north of the landfill and provided the list wells identified by USGS to the RA contractor for incorporation into their sampling efforts. Unfortunately, the RA contractor was able to obtain permission to sample only two additional alluvial wells south of the site. The EPA is also conducting oversight of the RA contractor sampling of on-site monitoring wells and has need to utilize the USGS contract lab program for split radionuclide samples. The USGS has two project tasks under this QAPP:

- (1) conduct sampling of existing private wells in the vicinity of the site, and
- (2) collect and provide radionuclide analysis on split water samples during scheduled October 2013 on-site groundwater sampling.

	*		
1.4	Project/Task Description:		
	CERCLA APA Report	CERCLA SI	Brownfields Assessment
	Other: Remedial Investigation support	Pre-CERCLIS Site Screening	Removal Assessment
	Schedule: Field work is scheduled for	October-November, 2013	
1.5	Quality Objectives and Criteria for Measuremen	nt Data:	
a. Acc	euracy:		<ul> <li>Identified in attached table.</li> </ul>
	cision: presentativeness:		<ul> <li>Identified in attached table</li> <li>Identified in attached table.</li> </ul>
d. Cor	mpleteness:		<ul> <li>Identified in attached table.</li> </ul>
	mparability: Description:		■ Identified in attached table.
	•		
		bles from the identified private wells has been esta	
		owner consent. Of the subset of wells where access aboratory parameters is established. However, if the	
	still be able to make site Decisions based on a		the completeness goal is not met, El A
ma <sub>j</sub> z		ny of an of the foliating variation data.	
1.6	Special Training/Certification Requirements:		
	■ OSHA 1910		
	Special Equipment/Instrument Operator (d	describe below): na.	
	Other (describe below): na.		
1.7	Documentation and Records:		
	■ Field Sheets ■ Well	ll inventory form Site Maps	<ul> <li>Health and Safety Plan</li> </ul>
	<ul> <li>Chain of Custody and Analytical Services I</li> </ul>		nt / field logbook entry
■ Le	etter Report Photos		
	Cample de aumentation will follow EDA D	7 COD 2420 5	
	Sample documentation will follow EPA Re	egion / SOP 2420.5.	
		idled according to procedures identified in Table 2.	
	easurement and Data Acquisition:		
2.1	Sampling Process Design:		
Ra	andom Sampling Transect Sampling	■ Biased/Judgmental Sampling	Stratified Random Sampling
	earch Sampling Systematic Grid	Systematic Random Sampling	Definitive Sampling
	creening w/o Definitive Confirmation	Screening w/ Definitive Confirmation	
υu	imple		
		rivate wells will be biased/judgmental, with definitive	
proced	rures included in OSWER Directive 9345.0 -01A,	"Guidance for Performing Preliminary Assessments U	Jnder CERCLA", dated September 1991,
EPA/5 92-021		uidance for Performing Site Inspections Under CERCL	A", dated September 1992, EPA/540 -K-
74 <b>-</b> 04 i		r	
		ted for major and trace inorganic constituents (including	
		n), subject to access being granted by the owners. These	
		estlake site. All samples will be analyzed by the USGS New Contract laboratories (Test America in Aryada, CO	
Ior tota	al metals and radionucides which will be analyzed	ed by contract laboratories (Test America in Arvada, CO	) or Test America in Richinolia, w.A.).
		USGS will accompany EPA and RA contractors during	
		ntainers and process, preserve, and ship samples for isot	
labora	tory (Test America, Inc.) in Richmond, Washingto	on. The EPA will collect samples for the remaining anal	lytes which will be determined at the EPA

Matrix

# of Samples\*

Sample Summary Location

Analysis

m 1 1 5 1 .	11 Litt 1 . c 11 O.1 Li I	•	77 . 0 . 11	last to a t
	wells within about 6 miles of the site allow (<350 ft deep) bedrock wells.	groundwater	Up to 9 wells	Major and trace cations, major anions, nutrients, VOCs, isotope of Ra, Th, U.
selected by EPA contractor [con	e (12) on -site monitoring wells to be A for split sampling/oversight of RA rect term?] USGS only providing ort for radionuclides	Groundwater	12 monitoring wells	Isotopic Ra, Th, U
NOTE: QC sam	ples are not included with these totals. See	Γable 1 for a complete sar	nple summary.	
2.2 Samp	le Methods Requirements:			
Matrix	Sampling Method		EPA SO	P(s)/Methods
Offsite private water supply wells	Groundwater samples will be collected standard USGS protocols described in USGS National Field Manual. Both fi unfiltered metals will be analyzed recomples at the field site. Private wells will be sampled from tap and the well will be purged until at least has been removed and until field stabilized.	section 4.2 of the ltered and quiring filtration of closest to the well,	1996.	eld Manual Section 4.2 ov/owq/FieldManual/)
Onsite Monitoring wells	Groundwater samples will be collected approved RA contractor QAPP except process and analyze radionuclide samp	that USGS will		at QAPP the split sampling is conducted r RA contractor ??
at lab	Samples will be processed, preserved, http://water.usgs.gov/owq/FieldManual boratory (radionuclides). C will be maintained as directed by Regiples will be accepted according to Regiples will be accepted according to Regiples (Describe):  **Tical Methods Requirements:*  **Ticil Methods Requirements:*  **Ticil Methods Requirements:*  **Ticil Methods Requirements:*	Sample will be ship ion 7 EPA SOP 2420.4 on 7 EPA SOP 2420.1	ped under chain-of-custody to the U	ed in the USGS National Field Manual ISGS laboratory or USGS contract

### 2.5 Quality Control Requirements:

Not Applicable

Identified in attached table.

■ In accordance with the Generic Quality Assurance Project Plan for Superfund Integrated Assessment and Targeted Brownfields Assessment Program (Updated: October 2012).

Describe QC Samples to be collected:

For Task 1 (offsite background), one equipment blank using laboratory-grade DI water will be processed. One field replicate sample, and one VOC trip blank per shipment will be processed.

For Task 2 no QA samples are planned.

#### Other (Describe)

#### 2.6. Instrument/Equipment Testing, Inspection, and Maintenance Requirements :

Not Applicable

■ In accordance with the USGS National Field manual ( <a href="http://water.usgs.gov/owg/FieldManual">http://water.usgs.gov/owg/FieldManual</a>) and Missouri Water Science Center Water-Quality QA Plan (2013).

Other (Describe):

#### 2.7 Instrument Calibration and Frequency:

For Tasks 1 and 2, all field meters used for field measurements (pH, specific conductance, dissolved oxygen, turbidity) will be calibrated at least daily according to the USGS National Field Manual and using manufacture procedures. Temperature, specific conductance, pH, and specific conductance will be measured using a YSI-855 or YSI pro-plus multi-parameter meter using a flow-through chamber. Turbidity will be measured using a HACH turbidity meter.

Calibration of laboratory equipment will be performed as described in the specific published USGS Analytical schedule or lab code referenced in attached Table 1 and USGS laboratory QAPP available at the USGS National Water Quality website at URL <a href="http://www.nwql.cr.usgs.gov/">http://www.nwql.cr.usgs.gov/</a>.

Other (Describe):

#### 2.8 Inspection/Acceptance Requirements for Supplies and Consumable

For Tasks 1 and 2, all sample containers will meet USGS criteria for cleaning procedures for low-level chemical analysis and be provided by the USGS National Water-quality laboratory. Major and trace cations, and radionuclide samples will be preserved to pH <2 using ultrex ™ nitric acid. Nutrients will be preserved by chilling. Disposable capsule filters that are supplied by the USGS Nation Water Quality laboratory and certified for use for trace metals and radionuclides will be used for processing dissolved inorganic constituents and radionuclides.

Other (Describe):

#### 2.9 Data Acquisition Requirements:

Not Applicable

■ In accordance with the Generic Quality Assurance Project Plan for Superfund Integrated Assessment and Targeted Brownfields Assessment Program (Updated: October 2012).

Previous data/information pertaining to the site (including other analytical data, reports, photos, maps, etc., which are referenced in this QAPP) have been compiled by EPA and/or contractor(s) from other sources. Some of that data has not been verified by EPA and/or its contractor(s); however, the information will not be used for decision-making purposes by EPA without verification by an independent professional qualified to verify such data/information.

Other (Describe):

#### 2.10 Data Management:

 All laboratory data acquired will be managed in accordance with the USGS Missouri Water Science Center Data Management Plan (2010) and Water Quality QA plan (2013) and stored in the USGS National Water Information System (NWIS).
 Other (Describe):

#### 3.0 Assessment and Oversight:

#### 3.1 Assessment and Response Actions:

Peer Review

Management Review

Field Audit

Lab Audit

■ Water-quality data collected and provided by the USGS under tasks 1 and 2 undergo a stringent review process described in the USGS National Field Manual (<a href="http://water.usgs.gov/owq/FieldManual/">http://water.usgs.gov/owq/FieldManual/</a>) and the USGS National Water Quality Laboratory QA Plan (<a href="http://nwql.usgs.gov/quality.shtml">http://nwql.usgs.gov/quality.shtml</a>). Contract laboratory radionuclide data is first reviewed by the contract laboratory according to their QA plan, then the complete data package is reviewed and by the USGS Laboratory. The data is reviewed by the USGS project chief, and finally, the data will be reviewed and approved by the USEPA project chief.

\*note -- In addition, for task 2, the USGS will have an external data validator experienced with radionuclide data validate both the USGS contract laboratory radiochemical data packet and the RA contractor radiochemical data packet.

Other (Describe):

#### 3.1A Corrective Action:

Corrective actions will be taken at the discretion of the EPA project manager, whenever there appears to be problems that could adversely affect
data quality and/or resulting decisions affecting future response actions pertaining to the site.

Other (Describe):

#### 3.2 Reports to Management:

<u>Task 1 (offsite sampling)</u> A letter report describing the sampling locations, problems encountered (with resolutions to those problems), and individual analytical results and a summary of the analytical results will be provided for task 1. This will include complete analytical data packages as attachments, from the USGS contract laboratories including reviews of external contract laboratory data by the USGS laboratory will be included.

<u>Task 2 (onsite split sampling for radionuclides)</u>. The complete radionuclide data package, including data validation review of the external contract laboratory, will be provided to the USEPA project manager. Because USGS is only providing analytical support for radionuclides, no additional narrative/report is schedule. USGS will prepare a letter report summarizing observations from field split sampling activities for submittal to the EPA project manager.

Reports prepared by the EPA, will be prepared in general accordance with the Generic Quality Assurance Project Plan for Superfund Integrated Assessment and Targeted Brownfields Assessment Program (Updated: October 2012).

■ Other (Describe):

#### 4.0 Data Validation and Usability:

#### 4.1 Data Review, Validation, and Verification Requirements:

Identified in attached table.

Data review and verification will be performed in accordance with standard USGS laboratory QA Plan at <a href="http://nwql.usgs.gov/quality.shtml">http://nwql.usgs.gov/quality.shtml</a> Radionuclide data for both task 1 and task 2 will be validated done by an external independent radiochemical data validator. After validation, the USGS project chief will review all data, QC data, and laboratory validation comments, and review the data in context of known groundwater geochemistry and historical data from the USGS laboratory or contract laboratory will not be formally validated other than the USGS laboratory and contract data review.

Other (Describe):

#### 4.2 Validation and Verification Methods:

Identified in attached table.

- Data generated by the USGS National Quality Laboratory will be reviewed and verified according to the laboratory QA Plan at <a href="http://nwql.usgs.gov/quality.shtml">http://nwql.usgs.gov/quality.shtml</a> before electronic transmittal to the local USGS office NWIS database.
- After review by the USGS laboratory, data is transmitted electronically to the local USGS office and the USGS project chief will reconcile laboratory data with field measurements and field notes according to the Missouri Water Science Center Water Quality QA Plan (2013). This includes comparison of sample dates, times, descriptions on field sheets and any anomalies documented. The USGS project chief also will review results of field replicates, blanks, and laboratory control samples to ensure they are acceptable for transmittal to EPA.
- The EPA site manager will inspect the data to provide a final review. The EPA site manager will review the data, if applicable, for laboratory spikes and duplicates, laboratory blanks, and the field blank to ensure that they are acceptable. The EPA site manager will also compare the sample descriptions with the field sheets for consistency and will ensure that any anomalies in the data are appropriately documented.

Other (Describe):

### 4.3 Reconciliation with User Requirements:

Identified in attached table

■ If data quality indicators do not meet the project's requirements as outlined in this QAPP, the data may be discar ded and re-sampling or reanalysis of the subject samples may be required by the EPA site manager.

Other (Describe):

		Table 1	: Sample Sumi	mary				
e: West Lak	e Landfill	The second s	City: Bridge	ton, MO	( Prop. )			
oject Manag	er: J. Schumach	ner .			Date: October, 2013			
Matrix	Location	Purpose	Depth or other Description	Requested Analysis	Sampling Method	USGS Analytical Method/SOP		
луѕие backgro	una water quanty in	tne attuviat ana Bo	еагоск адицег					
Water	Private wells	Assess background concentrations	Various or unknown	1- Dissolved major & trace inorganics 2- Dissolved Nutrients 3- Total metals (Sb, As, Ba, Be, Cd, Cr, Co, Cu, Fe, Pb, Mn, Ni, Se, Ag, II, V, Zn) 4- Dissolved U, Th, Ra, isotopes 5- Total U, Th, Ra isotopes 6- VOCs	NFM Sec 4.2	I- SH1260 +		
Water Blank	Private well  Blank	QC To assess reproducibility in lab and contamination from field equipment * sample processing	1-QC Replicate  1-Equipment blank	1- Dissolved major & trace inorganics 2- Dissolved Nutrients 3- Total metals (Sb, As, Ba, Be, Cd, Cr, Co, Cu, Fe, Pb, Mn, Ni, Se, Ag, Tl, V, Zn) 4- Dissolved U, Th, Ra, isotopes 5- Total U, Th, Ra isotopes 6- VOCs	USGS NFM Sec 4.2	1- SH1260 + LC3132 2- SH 2755 3- EPA 200.7 4- LC1472 (Th), LC1366 (U), LC2164 (Ra), LC1364 (Ra) 5- LC2631 (Th), LC2637 (U), LC2789 (Ra), LC2624 (Ra) 6- SH2020		
		contamination during shipping		·		I- SH2020		
it sampling of	RA contractor with	EPA R7 (note USC	SS providing anal	ytical support for radionucli	des only)			
Water	On-Site Monitoring wells	Verify RA contractor data	Various	<ul><li>1- Dissolved U, Th, Ra, isotopes.</li><li>2- Total U, Th, Ra isotopes</li></ul>	Approved RA QAPP with processing, according to USGS NFM Sec 4.2 °	1- LC1472 (Th), LC1366 (U), LC2164 (Ra), LC1364 (Ra) 2- LC2631 (Th), LC2637 (U), LC2789 (Ra), LC2624 (Ra)		
	Matrix  Offsite backgro  Water  Water  Blank	Matrix Location  Offsite background Water quality in  Water Private wells  Water Private well  Blank Blank  Blank  it sampling of RA contractor with  Water On-Site	Water Private well Private well Processing  Water Private well Private well Private well Processing  Water Private well Private Water Private well P	Private well Secure to assess reproducibility in lab and contamination from field equipment * sample processing  Assess contamination during shipping it sampling of RA contractor with EPA R7 (note USGS providing anal Water On-Site Verify RA Various  City: Bridge.  Activity/ASR Backg Backg Depth or other Description  Depth or other Description  Assess background concentrations  Various or unknown  1-QC Replicate To assess reproducibility in lab and contamination from field equipment * sample processing  Assess contamination during shipping it sampling of RA contractor with EPA R7 (note USGS providing anal Water On-Site Verify RA Various	Matrix   Location   Purpose   Depth or other   Description	City: Bridgeton, MO		

U.S. Geological Survey, variously dated, National field manual for the collection of water-quality data: U.S. Geological Survey Techniques of Water-Resources Investigations, book 9, chaps. A1-A9, available online at <a href="http://pubs.water.usgs.gov/twri9A">http://pubs.water.usgs.gov/twri9A</a>.

B- Total metals will be done by USGS contract laboratory (Test America, Inc., in Arvada Colorado), radionuclides are done by Test America, Inc. in Richland, Washington.

C- For radionuclides, USGS will follow RA approved QAPP for purging and sampling which will be done by the RA contractor, but use USGS sample supplies and USGS processing, and the USGS contract laboratory. Split samples for other analytes will be processed and submitted to the EPA R7 laboratory by EPA field personnel or contractors.

		27 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Tab	le 2: Data Quality	Objective Sur	nmary						
Site Nam	e: West La	ke Landfill	l	City: Bridgeton, MO								
START I	Project Mai	nager: NA		Activity/ASR #:	6163			Date: July, 2013				
	Analytical			Data Quality Measur	ements		Sample	Data				
Analysis	Method	Accuracy	Precision	Representativeness	Completeness	Comparability	Handling Procedures	Management Procedures				
				WAT (Groundwater, D	\$25000000000000000000000000000000000000							
Task 1 major and trace inorganics, nutrients, VOCs, and isotopic Ra, Th, U	see Table 1	per analytical method	per analytical method	Biased/judgmental sampling based on professional judgment of the sampling team	50% of wells identified, and 90% for all analytes of wells sampled.	Standardized USGS procedures for sample collection and analysis will be used	See Section 2.3 of QAPP	See Section 2.10 of QAPP form				
Task 2 Isotopic Ra, Th, U	see Table 1	per analytical method	per analytical method	Locations of split sampling with RA contractor to be determined by EPA project chief. Samples collected in conjunction with EPA	90%;	Standardized USGS procedures for sample processing and analysis will be used. Samples will be collected (well purging) according to approved RA contractor QAPP	See Section 2.3 of QAPP	See Section 2.10 of QAPP form				

## **Sampling Narrative**

#### Introduction

The United States Environmental Protection Agency (EPA) Region 7 has request assistance from the U.S. Geological Survey (USGS) Missouri Water Science Center (MWSC) to (1) identify and conduct sampling of offsite private, commercial, and possibly public-supply wells in the alluvial and shallow bedrock aquifer in the vicinity of the Westlake Landfill site, and (2) provide analytical capability for the radionuclide analysis (isotopes of Ra, Th, and U) of split samples to be collected from onsite monitoring wells as part of the EPA oversight of RA contractor groundwater sampling.

The purpose of the offsite sampling is to provide additional data to assist with the determination of background water quality in the alluvial and shallow bedrock aquifer at the site. The purpose of the onsite sampling is routine EPA oversight of the RA contractor and the EPA will utilize the USGS analytical service contract for isotopic Ra, Th, and U analysis of split samples collected by the EPA and USGS field team.

The Quality Assurance Project Plan (QAPP) identifies the site-specific features and addresses elements of the sampling strategy and analytical methods proposed for this investigation.

#### **Site Location**

Bridgeton, MO.

#### Site Description

Contaminants have been found in the groundwater within the alluvial aquifer and shallow bedrock aquifer beneath the West Lake Landfill, some of which, can also occur naturally in geologic materials, including radium and arsenic. Monitoring wells at the site are in proximity to landfill materials and pumping from a leachate collection system at the adjacent Bridgeton Landfill complicates identification of upgradient wells and, therefore, establishing background water quality using only site data difficult. Nearby private water-supply wells will be sampled to attempt to quantify naturally occurring levels of chemical constituents. The offsite wells will be sampled for dissolved major and trace cations and major anions (Cl, F, SO4), total metals, total VOCs, and dissolved and total isotopes of Ra, Th, and U.

A review of MDNR and USGS records and a cursory field reconnaissance of the vicinity in June, 2013 confirmed the presence of some private wells in the alluvium and bedrock in the vicinity of the Westlake Landfill site (fig. 1). In July, 2013, the EPA sampled six of the private wells in the alluvial aquifer north of the Westlake site and during August, 2013, the RA contractor sampled two of the alluvialwells south of the site (fig. 1). Because 8 offsite alluvial wells have been sampled, the focus of the USGS task 1 activity will be to locate and sample private bedrock wells in the vicinity of the site. During the June, 2013, reconnaissance, the USGS identified 6 bedrock wells and confirmed that a 7<sup>th</sup> bedrock well (former public-supply well at the Timbercrest Subdivision) had been abandoned. Wells within a 5-mi (miles) radius of the site with known or suspected completion in the Mississippian-age (Springfield Plateaus aquifer), and in a similar setting of near the end of local flow paths within the bedrock aquifer are preferred. However, based on the paucity of sampling points in this mostly urban area, any bedrock wells identified are candidates for sampling. A map of private alluvial and shallow bedrock wells in the vicinity of the site is provided as figure 1. The USEPA sampled wells C1, C2, C4, C5, C6, and C7 in June and the RA contractor sampled wells

Up to 9 offsite private wells may be sampled with preference given to bedrock wells. At least 6 bedrock wells were identified in the June, 2013 general reconnaissance of the area by the USGS (fig. 1). In addition, the USGS NWIS database includes data from two domestic wells of suitable depth (less than 350 ft) that were sampled in the 1930s and 1940s. A reconnaissance of the former locations of these two older wells will be done as well as a review of 1950s era topographic maps to identify older homes.




Figure 1. Status of known offsite private water supply wells in the vicinity of the Westlake Landfill.

ALV = alluvial well BED = bedrock well EPA = EPA July 2013 sample

RA = Remedial Action contractor August 2013, sample

NS = not sampled

UK = well location or current existence unknown

#### **Previous Investigations**

The USGS provided the list of all wells identified by the USGS during the June, 2013, to the EPA who shared the list with the RA contractor. During July, 2013, the USEPA was able to get permission to sample 6 of 7 private wells completed in the Missouri River alluvium located north of the site. In August, 2013, the RA contractor was able to obtain permission to sample two alluvial wells south of the site (fig. 1) but refused access to sample the remaining alluvial or bedrock wells. The EPA has asked the USGS to attempt to obtain permission to sample the remaining wells and locate additional wells in the area that might be sampled for determining background water quality..

#### Sampling Strategy and Methodology

The groundwater samples from the wells will be collected from taps/spigots located nearest the wellhead and prior to any in-home water treatment system. The wells will be purged according to protocols for sampling in the USGS National Field Manual (<a href="http://nwql.usgs.gov/quality.shtml">http://nwql.usgs.gov/quality.shtml</a>). Purging general will be done to remove at least one well volume (estimated) and until field parameters of temperature (within 0.5 degrees C), specific conductance (within 2 percent), pH (within 0.25 units) are stable over three consecutive readings taken no less than 0.2 well volumes apart.

An abbreviated USGS well inventory field sheet (attached) will be completed to document each groundwater sample location. In addition, a ground-water water quality field sheet (attached) is compelted for each groundwater sample to document well purging, field measurements, and sampling information. Water samples were be processed and preserved and shipped to the USGS National Water Quality Laboratory (dissolved major and trace inorganics, nutrients, VOCs), the USGS contract laboratory in Arvada, Colorado (total metals), or the USGS contract laboratory in Richland, Washington (radionuclides).

#### **Quality Control Samples**

Task 1: To evaluate contamination during sample collection and processing, a field equipment blank will be processed at one well sample site using inorganic blank water or VOC-free pesticide grade water (VOCs). A field replicate sample also will be collected from one well and analyzed for all analytes. A trip blank (supplied by the USGS laboratory) also will be included with each VOC shipment to track possible contamination during shipping.

Task 2: USGS is only providing analytical support for radionuclides for the routine EPA R7 oversight/split sampling of the RA contractor monitoring well sampling. USGS will accompany EPA oversight personnel and provide bottles, and process, preserve, and ship the radionuclide samples.

#### Analytical Methods

All samples will be analyzed by prublished EPA methods (radionuclides, and total metals) or published USGS methods that are standard EPA or modified EPA methods. Standard reporting levels will be used. USGS VOC reporting levels are in the 0.2 ug/L range for most analytes, 1 ug/L or less for most dissolved metals, 0.5 mg/L for major cations and anions, and 0.1 mg/L or less for nutrients. Copies of the USGS laboratory schedules and lab codes with reporting levels and method codes are attached. A standard USGS analytical services request form (generated electronically) will be utilized for all samples.

#### References

- U.S. Geological Survey, variously dated, National field manual for the collection of water-quality data: U.S. Geological Survey Techniques of Water-Resources Investigations, book 9, chaps. A1-A9, available online at <a href="http://pubs.water.usgs.gov/twri9A">http://pubs.water.usgs.gov/twri9A</a>.
- U.S. Geological Survey, Missouri Water Science Center, 2012, Quality Assurance Plan, Missouri Water Science Center water-quality activities: 23 p.
- U.S. Geological Survey, Missouri Water Science Center, 2010, Missouri Water Science Center data management plan, 9 p.



			Parameter	f					NELAP	
Analyte	Source	e Lab Code	Code	Method	CAS Number	RL	Unit	RL Type	Cert	Container ID
USGS SH 2160										
Antimony	U	1785	1095	PLM43	7440-36-0	0.027	ug/L	LTMDL		53 (FA)
Arsenic	U	3122	1000	PLM10	7440-38-2	0.04	ug/L	ltmdl		53 (FA)
Barium	U	641	1005	PLA11	7440-39-3	0.3	ug/L	ltmdl		53 (FA)
Beryllium	U	655	1010	PLA11	7440-41-7	0.1	ug/L	ltmdl		53 (FA)
Boron	U	2110	1020	PLA13	7440-42-8	1	ug/L	ltmdl		53 (FA)
Cadmium	U	1788	1025	PLM43	7440-43-9	0.016	ug/L	LTMDL		53 (FA)
Calcium	U	659	915	PLA11	7440-70-2	0.022	mg/L	ltmdl		53 (FA)
Chloride	U	1571	940	IC022	16887-00-6	0.06	mg/L	ltmdl	С	55 (FU)
Chromium	U	3126	1030	PLM10	7440-47-3	0.07	ug/L	ltmdl		53 (FA)
Cobalt	U	3124	1035	PLM10	7440-48-4	0.023	ug/L	ltmdl		53 (FA)
Copper	U	3128	1040	PLM10	7440-50-8	0.8	ug/L	ltmdl		53 (FA)
Fluoride	U	651	950	IC003	16984-48-8	0.04	mg/L	ltmdl		55 (FU)
ICP Mass Spectrometry (ICPMS) setup	U	2181	L2181				unsp	mrl		53 (FA)
Inductively coupled plasma (ICP) setup	U	2002	L2002				unsp	lrl		53 (FA)
Iron	U	645	1046	PLA11	7439-89-6	4	ug/L	ltmdl		53 (FA)
Lead	U	1792	1049	PLM43	7439-92-1	0.025	ug/L	ltmdl		53 (FA)
Lithium	U	664	1130	PLA11	7439-93-2	0.05	ug/L	ltmdl		53 (FA)
Magnesium	U	663	925	PLA11	7439-95-4	0.011	mg/L	ltmdl		53 (FA)
Manganese	U	1793	1056	PLM43	7439-96-5	0.15	ug/L	ltmdl		53 (FA)
Molybdenum	U	1794	1060	PLM43	7439-98-7	0.014	ug/L	LTMDL		53 (FA)
Nickel	U	3130	1065	PLM10	7440-02-0	0.09	ug/L	ltmdl		53 (FA)
pH, laboratory	U	68	403	EL006		0.1	рН	mrl		55 (RU)
Potassium	U	2774	935	PLO02	2023695	0.004	mg/L	ltmdl		53 (FA)
Silica	U	667	955	PLA11	7631-86-9	0.018	mg/L	ltmdl		53 (FA)
Silver	U	1796	1075	PLM43	7440-22-4	0.005	ug/L	LTMDL		53 (FA)
Sodium	U	675	930	PLA11	7440-23-5	0.06	mg/L	ltmdl		53 (FA)
specific conductance, laboratory	U	69	90095	WHT03		5	uS/cm	mrl		55 (RU)
Strontium	U	652	1080	PLA11	7440-24-6	0.2	ug/L	ltmdl		53 (FA)
Sulfate	U	1572	945	IC022	14808-79-8	0.09	mg/L	ltmdl	С	55 (FU)
Thallium	U	2508	1057	PLM40	7440-28-0	0.01	ug/L	ltmdl		53 (FA)
Vanadium	U	653	1085	PLA11	7440-62-2	0.6	ug/L	ltmdl		53 (FA)
Zinc	U	3138	1090	PLM10	7440-66-6	1.4	ug/L	ltmdl		53 (FA)

			Parameter	•					NELAP	
Analyte	Sourc	e Lab Code	Code	Method	CAS Number	RL	Unit	RL Type	Cert	Container ID
Lab Code 3132 Dissolved Selenium										
Selenium	U	3132	1145	PLM10	7782-49-2	0.03	ug/L	ltmdl		53 (FA)
SH 2755 Dissolved Nutrients										
Nitrogen, ammonia as N	U	3116	608	48	7664-41-7	0.01	mg/L	ltmdl	С	54 (FCC)
nitrogen, nitrite	U	3117	613	49	14797-65-0	0.001	mg/L	mdl	С	54 (FCC)
nitrogen, nitrite + nitrate	U	3156	631	RED01		0.04	mg/L	mdl		54 (FCC)
Total nitrogen (NH3+NO2+NO3+Organic), filtered	U	2754	62854	CL063	17778-88-0	0.05	mg/L	ltmdl		54 (FCC)
phosphorus, phosphate, ortho	U	3118	671	48	14265-44-2	0.004	mg/L	ltmdl	С	54 (FCC)
Lab Code 1472 Dissolved Thorium isotopes										
Thorium-228		1472	61738	AS068	14274-82-9	0.4	pCi/L	sslc		1-L FUR
Thorium-230		1472	26503	AS076	14269-63-7	0.4	pCi/L	sslc		1-L FUR
Thorium-232		1472	75976	AS084	7440-29-1	0.4	pCi/L	sslc		1-L FUR
Lab Code 1366 Dissolved Uranium isotopes										
uranium-234		1366	22610	AS089	13966-29-5	0.1	pCi/L	sslc		1-L FUR
uranium-235		1366	22620	AS101	15117-96-1	0.1	pCi/L	sslc		1-L FUR
uranium-238		1366	22603	AS105	7440-61-1	0.1	pCi/L	sslc		1-L FUR
Lab Code 2164 Dissolved Radium-224 and 226	isotopes									
Radium-224		2164	50833	AS056	13233-32-4	1	pCi/L	sslc		1-L FUR
Radium-226		2164	9503	AS060	13982-63-3	1	pCi/L	sslc		1-L FUR
Lab Code 2164 Dissolved Radium-228										
Radium-228		1364	81366	3	15262-20-1	1	pCi/L	sslc		1-L FUR
Lab Code 2631 Total Thorium isotopes										
Thorium-228		2631	22505	AS069	14274-82-9	0.4	pCi/L	sslc		1-L RUR
Thorium-230		2631	26501	AS077	14269-63-7	0.4	pCi/L	sslc		1-L RUR
Thorium-232		2631	22501	AS085	7440-29-1	0.4	pCi/L	sslc		1-L RUR
Lab Code 2637 Total Uranium isotopes										
uranium-234		2637	22606	AS094	13966-29-5	0.1	pCi/L	sslc		1-L RUR
uranium-235		2637	22622	AS102	15117-96-1	0.1	pCi/L	sslc		1-L RUR
uranium-238		2637	22601	AS110	7440-61-1	0.1	pCi/L	sslc		1-L RUR
Lab Code 2164 Dissolved Radium-224 and 226	isotopes									
Radium-224		2789	24501	AS057	13233-32-4	1	pCi/L	sslc		1-L RUR
Radium-226		2789	50838	AS061	13982-63-3	1	pCi/L	sslc		1-L RUR

	150 Sept. 150 Se	Parameter						NELAP	
Analyte	Source Lab Code	Code	Method	CAS Number	RL	Unit	RL Type	Cert	Container ID
Lab Code 2624 Total Radium-228									
Radium-228	2624	11501	BC040	15262-20-1	1	pCi/L	sslc		1-L RUR
SH 2020 Volatile Organic Compounds									
1,2,3,4-Tetramethylbenzene		49999	GCM66	488-23-3	0.1	ug/L	lri		46 (GCV)
1,2,3,5-Tetramethylbenzene		50000	GCM66	527-53-7	0.08	ug/L	lrl		46 (GCV)
2-Butanone		81595	GCM66	78-93-3	1.6	ug/L	lrl		46 (GCV)
trans-1,4-Dichloro-2-butene		73547	GCM66	110-57-6	2	ug/L	irl		46 (GCV)
2-Hexanone		77103	GCM66	591-78-6	0.6	ug/L	lri		46 (GCV)
4-Methyl-2-pentanone		78133	GCM66	108-10-1	0.32	ug/L	lrl		46 (GCV)
Acetone		81552	GCM66	67-64-1	3.4	ug/L	lrl		46 (GCV)
Acrylonitrile		34215	GCM66	107-13-1	0.56	ug/L	lrl		46 (GCV)
Benzene		34030	GCM66	71-43-2	0.026	ug/L	lrl	С	46 (GCV)
1,2,3-Trichlorobenzene		77613	GCM66	87-61-6	0.06	ug/L	lrl		46 (GCV)
1,2,3-Trimethylbenzene		77221	GCM66	526-73-8	0.06	ug/L	Irl		46 (GCV)
1,2,4-Trichlorobenzene		34551	GCM66	120-82-1	0.08	ug/L	Irl		46 (GCV)
1,4-Bromofluorobenzene (surrogate)		99834	GCM66	460-00-4		pct	Irl		46 (GCV)
Bromobenzene		81555	GCM66	108-86-1	0.022	ug/L	Irl		46 (GCV)
Chlorobenzene		34301	GCM66	108-90-7	0.026	ug/L	Irl	С	46 (GCV)
Ethylbenzene		34371	GCM66	100-41-4	0.036	ug/L	Irl	С	46 (GCV)
1,3-Dichlorobenzene		34566	GCM66	541-73-1	0.024	ug/L	Irl	С	46 (GCV)
Butylbenzene		77342	GCM66	104-51-8	0.08	ug/L	Irl		46 (GCV)
n-Propylbenzene		77224	GCM66	103-65-1	0.036	ug/L	Irl		46 (GCV)
1,2-Dichlorobenzene		34536	GCM66	95-50-1	0.028	ug/L	Irl	С	46 (GCV)
1,4-Dichlorobenzene		34571	GCM66	106-46-7	0.026	ug/L	Irl	С	46 (GCV)
sec-Butylbenzene		77350	GCM66	135-98-8	0.034	ug/L	Irl		46 (GCV)
tert-Butylbenzene		77353	GCM66	98-06-6	0.06	ug/L	Irl		46 (GCV)
Bromoethene		50002	GCM66	593-60-2	0.12	ug/L	Irl		46 (GCV)
Bromoform		32104	GCM66	75-25-2	0.1	ug/L	Irl	С	46 (GCV)
Hexachlorobutadiene		39702	GCM66	87-68-3	0.08	ug/L	Irl		46 (GCV)
Carbon disulfide		77041	GCM66	75-15-0	0.1	ug/L	irl		46 (GCV)
Tetrachloromethane		32102	GCM66	56-23-5	0.06	ug/L	Irl	С	46 (GCV)
Chloroform		32106	GCM66	67-66-3	0.03	ug/L	Irl	С	46 (GCV)
Isopropylbenzene		77223	GCM66	98-82-8	0.042	ug/L	Irl		46 (GCV)

		Parameter	•					NELAP	
Analyte	Source Lab Code	Code	Method	CAS Number	RL	Unit	RL Type	Cert	Container ID
1,1,1,2-Tetrachloroethane		77562	GCM66	630-20-6	0.04	ug/L	lrl		46 (GCV)
1,1,1-Trichloroethane		34506	GCM66	71-55-6	0.03	ug/L	lrl	С	46 (GCV)
1,1,2-Trichlorotrifluoroethane		77652	GCM66	76-13-1	0.022	ug/L	lrl		46 (GCV)
1,2-Dibromoethane		77651	GCM66	106-93-4	0.028	ug/L	lrl		46 (GCV)
1,2-Dichloroethane-d4 (surrogate)		99832	GCM66	17060-07-0		pct	iri		46 (GCV)
1,2-Dichloroethane		32103	GCM66	107-06-2	0.08	ug/L	lrl	С	46 (GCV)
Hexachloroethane		34396	GCM66	67-72-1	0.12	ug/L	lrl		46 (GCV)
1,1,2,2-Tetrachloroethane		34516	GCM66	79-34-5	0.14	ug/L	lrl	С	46 (GCV)
Chloroethane		34311	GCM66	75-00-3	0.06	ug/L	lrl	С	46 (GCV)
Diethyl ether		81576	GCM66	60-29-7	0.1	ug/L	lrl		46 (GCV)
Ethyl tert-butyl ether		50004	GCM66	637-92-3	0.032	ug/L	lrl		46 (GCV)
cis-1,2-Dichloroethylene		77093	GCM66	156-59-2	0.022	ug/L	Irl		46 (GCV)
Tetrachloroethylene		34475	GCM66	127-18-4	0.026	ug/L	Irl	С	46 (GCV)
trans-1,2-Dichloroethylene		34546	GCM66	156-60-5	0.018	ug/L	Irl		46 (GCV)
Trichloroethylene		39180	GCM66	79-01-6	0.022	ug/L	iri	С	46 (GCV)
1,1-Dichloroethane		34496	GCM66	75-34-3	0.044	ug/L	Irl	С	46 (GCV)
Tetrahydrofuran		81607	GCM66	109-99-9	1.4	ug/L	Irl		46 (GCV)
Diisopropyl ether		81577	GCM66	108-20-3	0.06	ug/L	Irl		46 (GCV)
m- and p-Xylene		85795	GCM66	179601-23-1	0.08	ug/L	iri	С	46 (GCV)
1,3,5-Trimethylbenzene		77226	GCM66	108-67-8	0.032	ug/L	iri		46 (GCV)
Ethyl methacrylate		73570	GCM66	97-63-2	0.2	ug/L	Irl		46 (GCV)
Methyl methacrylate		81597	GCM66	80-62-6	0.3	ug/L	iri		46 (GCV)
Methyl acrylonitrile		81593	GCM66	126-98-7	0.26	ug/L	iri		46 (GCV)
Bromochloromethane		77297	GCM66	74-97-5	0.06	ug/L	iri		46 (GCV)
Bromodichloromethane		32101	GCM66	75-27-4	0.034	ug/L	iri	С	46 (GCV)
Dibromochloromethane		32105	GCM66	124-48-1	0.12	ug/L	iri	С	46 (GCV)
Dichlorodifluoromethane		34668	GCM66	75-71-8	0.1	ug/L	iri		46 (GCV)
Trichlorofluoromethane		34488	GCM66	75-69-4	0.06	ug/L	iri	С	46 (GCV)
Methyl acrylate		49991	GCM66	96-33-3	8.0	ug/L	iri		46 (GCV)
Bromomethane		34413	GCM66	74-83-9	0.2	ug/L	iri		46 (GCV)
Chloromethane		34418	GCM66	74-87-3	0.1	ug/L	mrl		46 (GCV)
Methyl iodide		77424	GCM66	74-88-4	0.26	ug/L	Irl		46 (GCV)
tert-Butyl methyl ether		78032	GCM66	1634-04-4	0.1	ug/L	Irl		46 (GCV)

		Parameter						NELAP	
Analyte !	Source Lab Code	Code	Method	<b>CAS Number</b>	RL	Unit	RL Type	Cert	Container ID
Dibromomethane		30217	GCM66	74-95-3	0.05	ug/L	lri		46 (GCV)
Dichloromethane		34423	GCM66	75-09-2	0.04	ug/L	mrl	С	46 (GCV)
Naphthalene		34696	GCM66	91-20-3	0.18	ug/L	lri		46 (GCV)
Number of Tentatively Identified Compounds (TICs)		99871	GCM66			no.	lri		46 (GCV)
o-Xylene		77135	GCM66	95-47-6	0.032	ug/L	lri	С	46 (GCV)
4-Isopropyl-1-methylbenzene		77356	GCM66	99-87-6	0.06	ug/L	lri		46 (GCV)
1,2,3-Trichloropropane		77443	GCM66	96-18-4	0.12	ug/L	lri		46 (GCV)
1,3-Dichloropropane		77173	GCM66	142-28-9	0.06	ug/L	lri		46 (GCV)
2,2-Dichloropropane		77170	GCM66	594-20-7	0.06	ug/L	lrl		46 (GCV)
1,2-Dibromo-3-chloropropane		82625	GCM66	96-12-8	0.4	ug/L	lrl		46 (GCV)
1,1-Dichloropropene		77168	GCM66	563-58-6	0.04	ug/L	lri		46 (GCV)
3-Chloropropene		78109	GCM66	107-05-1	0.08	ug/L	Irl		46 (GCV)
cis-1,3-Dichloropropene		34704	GCM66	10061-01-5	0.1	ug/L	Irl	С	46 (GCV)
trans-1,3-Dichloropropene		34699	GCM66	10061-02-6	0.14	ug/L	Irl	С	46 (GCV)
1,2-Dichloropropane		34541	GCM66	78-87-5	0.026	ug/L	Irl	С	46 (GCV)
1,2,4-Trimethylbenzene		77222	GCM66	95-63-6	0.032	ug/L	lri		46 (GCV)
Set number		99827	GCM66			no.			46 (GCV)
Styrene		77128	GCM66	100-42-5	0.042	ug/L	lrl		46 (GCV)
tert-Pentyl methyl ether		50005	GCM66	994-05-8	0.06	ug/L	Irl		46 (GCV)
Toluene		34010	GCM66	108-88-3	0.02	ug/L	mrl	С	46 (GCV)
2-Chlorotoluene		77275	GCM66	95-49-8	0.028	ug/L	Irl		46 (GCV)
o-Ethyl toluene		77220	GCM66	611-14-3	0.032	ug/L	Irl		46 (GCV)
4-Chlorotoluene		77277	GCM66	106-43-4	0.042	ug/L	lrl		46 (GCV)
Toluene-d8 (surrogate)		99833	GCM66	2037-26-5		pct	lri		46 (GCV)
Vinyl chloride		39175	GCM66	75-01-4	0.06	ug/L	lrl	С	46 (GCV)
1,1,2-Trichloroethane		34511	GCM66	79-00-5	0.046	ug/L	irl	С	46 (GCV)
1,1-Dichloroethylene		34501	GCM66	75-35-4	0.022	ug/L	Irl	С	46 (GCV

Constitute   Con	Topographic Setting	Field ID		ENTORY FORM Site ID (LAT/IONG	(/SEQ NO.)	Project Number GR11SG00EJ80000
County   C	Country   Coun		Party	Date Inventoried	TR	
Use of water   Flood Plain   Hill Side   Hill Top   Valley Flat   Hill Top	Use of water   Hill Top   Valley Flat					1/4 1/4
Use of water	Use of water	atitude	Longitude	Quad Name	poorting poorting	
Domestic   Domestic   Domestic   Domestic   Upland Draw   Sink Hole   Domestic   Domestic   Upland Draw   Sink Hole   Domestic   Dom	MeMap; G=GPS; N=Dig Map  Domestic  Public Supply  Industrial  Irrigation  Unused  Stock  See of site  Observation  Withdrawal  Unused  Source of Construction Data  D=Comer, R=Regarded, D=Dniller, A=Other Geo/t, S=USS)  Withdrawal  L=Catanato  D=Comer, R=Regarded, D=Dniller, A=Other Geo/t, S=USS)  Withdrawal  D=Comer, R=Regarded, D=Dniller, A=Oth	at/I and Mathad			Flood Plain Hill Side	
Public Supply   Upland Draw   Sink Hole   Sink Hole   Sink Hole   Industrial   Irrigation   Unused   Unused   Pape MC: R=Rock/Stone; S=Steet:   Cher - Describe   Pape MC: R=Rock/Stone; S=Steet:   Cher - Describe   Type of Well Opening   X=Copen Hole, T=Sand Point; S=Screen:   Unused   Cher - Describe   Cher - Descr	Public Supply		1 1	<u> </u>	Hill Top Valley Flat	
Industrial   Irrigation   Umused   Stock   Seteel:   Speed Well Opening   Other - Describe   Pump Depth   Other - Describe   Stock   Seteel:   Speed Well Opening   Other - Describe   Stock   Seteel:   Speed Well Opening   Other - Describe   Stock   Seteel:   Speed Well Opening   Other - Describe   Second	Industrial	Owner			Upland Draw Sink Hole	
Irrigation   Unused   Stock   Use of site   Unused   Unused   Describe   P=PVC; R=Rock/Stone; S=Steet:   Type of Wall Opening   X=Open Hole; T=Sand Point, S=Screen;   Describe	Irrigation   Unused   Diter - Describe   Diter - Describe   P=PAC; R=Rock/Stone; S=Steet;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Open Hole; T= Sand Point: S = Screen;   Type of Web Opening   X = Opening   X				Wall Donth	Socing doub
Unused   Stock   Sto	Unused   Stock   See   See   Stock   See   Stock   See   Stock   See   Stock   See   See   Stock	ddress			Well Depth	asing depin
Stock   Stoc	Stock   Stoc	City/ Zip				
Stock   Visc of site   Date of Construction Data   Date   Time   Party   WL Meas   Corr (+/-)   Corr (-/+)   (bls)   Method   Status   D = Driver (describe)   Collection point   Sitart Purge   End Purge   Party   Purge   End Purge   Purge   Date   Collection point   Start Purge   End Purge   Date   Collection to well location with landmarks (roads, structures) and   Start Purge   Start	Stock   Use of site   Date of Construction   Date of Construction Data   Date of Construction Data   Date   Date of Construction Data   Date   Date of Construction Data   Date			Unused		
Observation   Withdrawal   Unused   Source of Construction Data   O = Owner, R = Reported; D = Driller, A = Other Govt; S = USSS	Observation   Withdrawal   Unused   Source of Construction Data   O = Owner; R = Reported; D = Driller, A = Other Govt; S = USSS	none		Stock	X = Open Hole; T = Sand Point; S = S	creen;
titude Method	titude Method   Other - Describe   Unused   Unused   Other (describe)   Source of Construction Data   O = Owner; R = Reported; D = Driller; A = Other Gov't; S = USGS    Water Level (WL) Measurements	revious Owner		<u></u>	Date of Construction	Pump Depth
Ititude Method   Chher - Describe   Unused   Unused   Chher (describe)   Source of Construction Data   O = Owner, R = Reported; D = Driller, A = Other Govt; S = USSS      Poescription   Process   Water Level (WL)   Measurements   Calib   MP   WL   WL   Well   E = Estimated   A = Airline   A =	Ititude Method   Georgia		<b>1000000000000000000000000000000000000</b>		Driller	
Source of Construction Data   O - Owner, R = Reported; D - Driller, A = Other Gov't; S = USGS	Source of Construction Data		Other - Describe	panning .		
Water Level (WL) Measurements  Calib MP WL WL Well E = Estimated A = Airline S = Steel Tape V = Calibrated elect tape Z = Other (describe)  Well Status D = Dry F = Flowing P = Pumping R = Recently Pumped  Water Samples Date Collection point time time Yield Cond Temp pH DO Remarks (smell, claring emarks: [How to access well head, special tools needed (wrenches) Sketch and directions to well location with landmarks (roads, structures) and	Water Level (WL) Measurements  Calib MP WL WL Well E-Estimated A - Airline S - Steel Tape V - Calibrated elect tape Z - Other (describe)  Well Status D - Dry F = Flowing P = Pumping R = Recently Pumped  Water Samples Date Collection point time time Yield Cond Temp pH DO Remarks (smell, clarity)  emarks: [How to access well head, special tools needed (wrenches) Sketch and directions to well location with landmarks (roads, structures) and		MP Height			A = Other Covit: S = LISCS
Water Level (WL) Measurements  Calib MP WL WL Well E= Estimated A = Airline S = Steel Tape V = Calibrated elect tape Z = Other (describe)  Well Status D = Dry F = Flowing P = Pumping R = Recently Pumped  Water Samples Date Collection point time time Yield Cond Temp pH DO Remarks (smell, clarity  emarks: [How to access well head, special tools needed (wrenches) Sketch and directions to well location with landmarks (roads, structures) and	Water Level (WL) Measurements  Calib MP WL WL Well E = Estimated A = Airline S = Steel Tape V = Calibrated elect tape Z = Other (describe)  Well Status D = Dry F = Flowing P = Pumping R = Recently Pumped  Water Samples Date Collection point Start Purge End Purge time Yield Cond Temp pH DO Remarks (smell, clarity emarks: [How to access well head, special tools needed (wrenches) Sketch and directions to well location with landmarks (roads, structures) and	THE CONTROL OF THE CO		Other (describe)	0 - Owner, K - Reported, D - Driller,	A - Other GOV t, 3 - GGGS
Date Time Party WL Meas Corr (+/-) Corr (-/+) (bls) Method Status A = Airline S = Steel Tape V = Calibrated elect tape Z = Other (describe)  Well Status D = Dry F = Flowing P = Pumping R = Recently Pumped  Water Samples Date Collection point time time Yield Cond Temp pH DO Remarks (smell, clarity permarks: [How to access well head, special tools needed (wrenches) Sketch and directions to well location with landmarks (roads, structures) and	Date Time Party WL Meas Corr (+/-) Corr (-/+) (bls) Method Status A = Airline S = Steel Tape V = Calibrated elect tape Z = Other (describe)  Well Status D = Dry F = Flowing P = Pumping R = Recently Pumped  Water Samples Collection point time time Yield Cond Temp pH DO Remarks (smell, clarity pmarks: [How to access well head, special tools needed (wrenches) Sketch and directions to well location with landmarks (roads, structures) and	MP Description				
Date Collection point time time Yield Cond Temp pH DO Remarks (smell, clarity and the condition of the condi	Date Collection point time time Yield Cond Temp pH DO Remarks (smell, clarity elemarks: [How to access well head, special tools needed (wrenches)  Sketch and directions to well location with landmarks (roads, structures) and					D = Dry F = Flowing P = Pumping
					Temp pH DO	Remarks (smell, clarity)
						(roads, structures) and
						(roads, structures) and
						(roads, structures) and



## U. S. GEOLOGICAL SURVEY GROUNDWATER QUALITY FIELD NOTES

NWIS RECORD NO \_\_\_\_\_

Station No		Stati	on Name					Field ID
Sample Date		Mean Sa	ample Time (	watch)		Ti	me Dat	um (eg. EST, EDT, UTC)
Sample Medium	_ Sampl	e Type Sample Pur	pose (71999)	) Pu	pose of	Site Visit	(50280	) QC Samples Collected? Y N
Project No.	*******************		Proje	ect Name				
Sampling Team			Tean	n Lead Sign	ature			Date
				ASUREM				
			T		D-	Value	Null	
	Parm				Re- mark	Value Quali-	Value Quali	
Property Water Level (see p. 8	Code	Method Code	Result	Units	Code	fier	fier	NWIS Result-Level Comments
for codes and units)								
Flow Rate	00059			gal/min				
Sampling Depth	00003			ft				
Depth to top of sampling interval	72015			ft blw Isd				
Depth to bottom of sampling interval	72016			ft blw Isd				
Temperature, Air	00020	THM04 (thermistor) THM05 (thermometer)		°C				
Temperature, Water	00010	THM01 (thermistor) THM02 (thermometer)	1	°C				
Specific Conductance	00095	SC001 (contacting sensor)	, <del> </del>	□S/cm				
Dissolved Oxygen	00300	SPC10 (Spectrophotometer) LUMIN (luminescent MEMBR (Amperometric)		mg/L				
Barometric Pressure	00025	in and it (v an poromouro)	†	mm Hg				
рН	00400	PROBE (electrode)		units				
ANC, unfiltered, incremental	00419	TT001		mg/L				
Alkalinity, filtered, incremental	39086	TT013		mg/L				
Carbonate, filtered, incremental	00452	TT019		mg/L				
Bicarbonate, filtered, incremental	00453	TT017		mg/L				
Hydroxide, filtered, incremental	71834	TT023		mg/L				
Turbidity [see attachment for codes]								
Redox potential (Eh)	63002			mvolts				
Hydrogen sulfide odor detected?	71875	SNIF1 (sniff test, acidified sample) SNIF2 (sniff test, non-acidified sample)	#	Yes No	M detect U non- detect			Sample acidified beforehand? yes no
Hydrogen sulfide, unfiltered, measured		ISE01 (electrode) KIT01 (Chemetrics) KIT02 (Hach)		mg/L				
Other								
Other								
		I I	SAMPLING	G INFORM				
Parameter Sampling Condition*	<b>Pcode</b> 72006					nforma		
. 0		Dump/Sampl						
Sampling Method*	82398	Sampler Mat						other
Sampler Type*	84164	Tubing Mate						
*see p. 8 for value	es				•			membrane
COMPILED BY:		CHECKED BY: Date			i	LOGGED	INTO NW	/IS BY: Date

November 2009 1 GW Form version 8.0

SAMPLING	CONDITIONS
Aquifer name	ft blw_lsd_msl_mp
Sampling point description	
GW Color: brown gray blue green yellow other	
GW Clarity: clear turbid muddy other	Foaming: Yes No
Sand Present: Yes No If yes, color of sand: Black Br	
GW Odor: Yes No describe	
Sample in contact with: atmosphere oxygen nitrogen other	·
Weather: <b>sky-</b> clear partly cloudy cloudy <b>precipitation</b> -	none light medium heavy snow sleet rain mist
wind- calm light breeze gusty windy est. wind speed	·
Observations:	mp. comporators very cold cool main. not
Observations.	
Sample Comments (for NWIS; 300 characters max.):	
Cample Commonta (Ior Avvic, Coo Characters max.).	
LABORATORY INFORMATION Sample Set ID	
SAMPLES COLLECTED:	
Nutrients:WCAFCCFCA Major cations:FARA	Major anions:FU
Mercury:FAMRAMWis. Hg Lab Lab pH/SC/ANC:	_RU
VOC: GCV ( vials) Organics:GCC filtered unfiltered	C18 Kansas OGRG Lab
Suspended solids:SUSO Turbidity:TBY	
Phenols:PHE Oil&Grease:OAG Methylene Blue Active Su	
Carbon:TPCNPIC filter1-vol filteredmL filter2-vol filtere  Radon:RURCV (Radon sample collection time:) Stable	
Radiochemicals: FUR RUR SUR FAR RAR R	
	(Lab) Other: (Lab)
	(Lab) Other:(Lab)
Microbiology:	
Laboratory Schedules:	
Lab Codes: add/delete add/delete	add/delete add/delete add/delete
Comments:	
Date shipped: Laboratory	Date shipped Laboratory
Date shipped: Laboratory	Date shipped Laboratory
**Notify the NWQL in advance if shipping potentially hazardous sam	ples—phone 1-866-ASK-NWQL or email LabLogin@usgs.gov

	ted by:			Location:				FIELD ID _	
Date		111	me: MI		BRATIONS/FII	ELD MEASUR	EMENTS		
TEMPER	ATURE Meter	make/model	***************************************	S	5/N	The	Thermistor S/N Thermometer ID		
Calibra	tion criteria: ± 1	percent or ± 0.	5 °C for liquid-fil	led thermomete	ers ± 0.2 °C for	thermistors		Local Meter ID:	
.ab Teste	d against NIS	T Thermome	ter/Thermisto	or? Y	N Dat	e:		±°C	
Measuren	nent Location	: FLOW-THR	U CHAMBER	SINGLE P	OINT AT	ft blw LSD	VERTICAL A	/G. OF POINTS	
Field Rea	dings # 1	#2	#3	#4	#5	MEDIAN:	°C Method	d Code Rema	rk Qualifier
-11 84-4-				C/N		Clastes de Na		Towns and towns	
								Type: GEL LIQUID	
Sample:	FILTERED U	NFILTERED	FLOW-THRU (	CHAMBER	SINGLE POIN	IT AT	TT DIW LSD	VERTICAL AVG. OF	_ POINTS
H Buffer	Buffer Temp	Theoretical	pH	pН	Slope	Millivolts		ection factors for buffers	applied? Y N
		pH from table	Before Adj.	After Adj.	1000		Local Meter ID:		
Н 7							pH Buffer	Lot No.	Expiration Date
H 7									
H 7							pH 7		
Н							pH 10		
Н							.11.4		
H							pH 4		
CHECK oH							Calibration Criteria:	: ± 0.1 pH units, ± 0.3 if S	GC <75us/cm
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			<u> </u>	<u> </u>					
	e: Flow-thru	chamber		at	_ ft blw lsd		. of poi	Local Meter ID:  Calibration Criteria: ± 3% for SC >100 □S/c	5 % for SC ≤100 ⊡S/cm o m
								AUTO TEMP COMP METER?	ENSATED Y N
						+		CORRECTION FACT	OR APPLIED? Y
			<del>                                     </del>			<del>                                     </del>		CORRECTION FACT	OR=
Field R	eadings #1 _	#2	#3	#4	_#5 <b>M</b> I	EDIAN:	<b>s/cm</b> Metho	od Code Rema	ark Qualifier
DISSO	LVED OXYGI	EN Meter ma	ake/model			S/N		Local Meter	
								ID:	
Sample	: Flow-thru	chamber Si	ngle point at	ft b	lw Isd Vertic	cal avg. of	points BOD	bottle Stirrer Used?	YN
Water-S	Saturated Air	Air-Saturate	d Water Air	Calibration	Chamber in W	ater Air Calib	oration Chamber	in Air Air Saturated	Water
Calibrat Temp		e Reading	Salinity Correc- tion	DO Before Adjust-	Adjust			lj. to mg/L D	
160		•	Factor	ment	ment Zen			Thermistor Check? Y  Date:	
								ate:	
Calibration	on Criteria: ± 0.2	mg/L I	OO saturatio	n 9				tor (100%)	
Field R	eadings #1	#2	<b>#</b> 3	#4	#5 <b>ME</b>	DIAN:	mg/L Method	I Code _ Rema	ark Qualifier
						3	_		GW Form version 8

TURBIDITY Meter make/model	S/N	Туре:	turbidimeter	submersib	le spectro	photometer
Sample: pump discharge line flow	-thru chamber single point at	ft blw LSD MSL	. MP Sei	nsor ID		
Sample: Collection Time: M	easurement Time: Measu	rement: In-situ/On-site	Vehicle Offic	ce lab NWQL	Other	
Sample diluted? Y N Vol. of dilu	tion water mL Sample vo	lume mL	Tupp	IDITY VALUE = A	/ ( <b>R</b> + <b>C</b> ) / C	
Lot Number or Expira Date Prepared Dat	- I - I	Initial Reading adjustment reading	after A=		IN DILUTED SA ION WATER, M	
Stock Turbidity Standard Zero Standard (DIM) Standard 1				ration Criteria: 0 Turbidity units		dity units or e measured chever
Standard 2			> 10	0 Turbidity units		
Standard 3						
Field Readings #1 #2 _	#3 #4	#5	mananang angkannan			
MEDIAN Parameter Code _	FNU NTU NTRU FNMU FNRU F.	fau fbu au <b>M</b> ethod cod	E	Remark	Qual	ifier
	WELL and WATER-LI	EVEL INFORMATI	ON			
WELL SPRING MONITOR SUPPLY				Water and V	Vell Depth	
				1sT	2ND	3RD (optional)
SUPPLY WELL PRIMARY USE: DOMESTIC PUBL Casing Material: Altitud	<del></del>		DTM/\			
Measuring Point: ft abv blw LSE	,	- Cut	DIW)			
Well Depth ft abv blw LSD MSL		= DTW from				
Sampling condition (72006) pumping (8) flo			•			
Water Level: ft blw LSD (72019) ft abv MSL (NAVD 1	ft blw MP (61055) ft abv MSL (NGVD 19 988) (62611) [enter the selected pcode or	929) (62610) Hold (for	well depth)			
Water Level Method: steel tape electric tape	airline other		tape leader			
Comments:		= Well dept	h below MP MP below LS)			
WATER-LEVEL DATA FOR (	 Gwsi		h below LSD			
DATE WATER LEVEL MEASURED (C235)	TIME	(C709)	WATER LEV CODE (C243		M	s
WATER LEVEL	MP SEQUENCE NO. (C248) (Mandatory if WL type=M)			below land surfac	meas.	sea level
WATER LEVEL NGVD 29	NAVD 88					
DATUM (C245) (Mandatory if WL type=S) National Geodetic Vertical Datum 0f	North American Other (See GWSI manual fo	or codes)				
1929	1988					
SITE STATUS FOR WATER A B C D	E F G H I J	M N O P	R S	T V	W X	z
LEVEL (C238) atmos. tide ice dry pressure stage	recently flowing nearby nearby injector injector problems flowing flowing nearby injector injector problems flowing injector injector injector problems flowing injector i	plugged measure- obstruct- pumping ment tion discontinued	pumped pumping	recently sub-	well affected by des- surface royed water	other
METHOD OF WATER-LEVEL A B					noyed water	
MEASUREMENT(C239)  A B  airline analog cal		M N O	R S T	V Z		
	airline mated ducer gage pres. gage cal logs		tape tape	elec. tape		
ACCURACY (C276)  O 1 2 9  foot tenth hun- not to dreth nearest foot	SOURCE OF WATER-LEVEL A	driller's geol-geophysi-memor	O R			
PERSON MAKING MEASUREMENT (C246)	MEASURING AGENCY (C247) (SOURCE)	RECOR WEB (C	D READY FOR (858)	Y C	P L	
(WATER-LEVEL PARTY)					proprietary; local no web only display we disp	no b

VEL	DI	IRGE	I OG

FIELD ID\_

Allowa	able Draw	/down:	<i>f</i> Start tim		ge meth	nod: s	randard l <b>End Time</b>	OW-FLOW	OTHER _	***************************************		
Time	Water Level blw MP LSD	Draw- down ft	Well Yield gpm	Pumping Rate gpm	Water Temp °C	Condu tivity □s/cr	units	Dis- solved oxygen	Turbidity		Comments [clarity, etc.]	
					***************************************	200 mm 1 m						
								<u></u>				
		10, 30										
				(MIN) (A)							MEDIAN VALUES	
											QUIESCENT PH	
								1			FINAL FIELD MEASURE-	
where: <b>V</b> is vo	lume of wat	V = 0.0408 F er in the well er column, in f	in gallons	l Volume =	I L	Paramet pH	ter Stability Criteria* (for more information see NFM Table 6.0-1)  ± 0.1 units (± 0.05 units if instrument display 2 or more digits to the right of the decimal)  ± 0.3 if SC <~75□S/cm					
<b>D</b> is in:	side Diamet	er of well, in i	nches				<b>Temperature (T)</b> ± 0.2° C (thermistor)			)		
<b>F</b> is ca	ising Volume	e Factor (see	table)		L	(SC)	± 5%, of SC < 100 □S/cm ± 3%, for SC > 100 □S/cm					
		tic water leve		feet	1 L		ed Oxygen (DO) ± 0.2 mg/L					
						Turbidity	# 10%, for TU< 100: ambient TU is < 5 or most groun water systems (visible TU > 5)  wable variation among 5 or more sequential field-measurement values					
	olume = (n)	(V) =	galloi	ns [Actual =	=	gal]		_			ept where noted):	
		I volumes to er in the well.		during purgi	ng		Distance to top of screen from LSD					
Q = estim	nated pumpi	ng rate =	gallons				+ MP (- if MP below LS)					
Approxim	nate purge ti	me = (purge v	volume)/ <b>Q</b> =		ninutes		(7 to 10 x diameter (inches) of the well)  [convert to feet]					
		2.0 3.0 4 0 0.16 0.37 0	0 4.5 5.0	6.0 8.0 10	.0   12.0   2 08   5.88   2		= Depth to	pump intak	e from MP			
Screened/Open Interval: TOP												
Bottom ft blw LSD MSL  Depth to Top of Sampling Interval ft blw LSD MSL												
		piing intervai ampling Inter				MSL	= Depth pu	mp set froi	m LSD MSI	L		
	Calculati						<u> </u>					

FIELD I	D	
FIELD I	D	

#### **ALKALINITY/ANC CALCULATIONS**

BEGINNING H <sub>2</sub> O TEMP °C				;	BEGI	NNING H2C	TEMP	°c		CALCULATIONS				
PH	<b>▲PH</b>	VOL ACID DC or mL	<b>▲ VOL ACID</b> DC OR mL	▲PH ▲ VOL ACID	PH	▲PH	VOL ACID DC OR mL	<b>▲VOL ACID</b> DC OR mL	▲ PH ▲ VOL ACID	_ ALKALINITY (mg/L as where:	ALKALINITY (mg/L as CaCO <sub>3</sub> ) = 50044 (B) (C <sub>a</sub> ) (CF) / V <sub>s</sub> where:  B = volume of acid titrant added from the initial pH to the bicarbonate equivalence point (near pH 4.5), in milliliters. To convert from digital counts to milliliters, divide by 800 (1.00 mL = 800 counts)  C <sub>a</sub> = concentration of acid titrant, in milliequivalents per milliliter (same as equivalents per liter, or N)			
										the bicarbonate equ milliliters. To conver				
										CF = Hach cartridg 1.01) [see OW				
					TATE OF THE PARTY					V <sub>s</sub> = volume of sam	ple, in milliliters	s		
		-				<u></u>								
					***************************************					For samples with ph	1 ≤ 9.2:			
									***************************************	BICARBONATE (mg/L	) = 61017 (B-2A	(C <sub>a</sub> ) (CF	) / V <sub>s</sub>	
								***************************************		CARBONATE (mg/L) =	= 60009 (A) (C <sub>a</sub> )	(CF) / V <sub>s</sub>		
								***************************************		where:  A = volume of acid titrant added from the initial pH to the carbonate equivalence point (near pH 8.3), in milliliters. To convert from digital counts to milliliters, divide by 800 (1.00 mL = 800 counts)				
										NOTE: For samples with pH > 9.2, these equations for			ons for	
										bicarbonate and carbo				
										Use the Alkalinity http://oregon.usg			[h44n = //	
										water.usgs.gov/u			reg.//	
		np	°C					_ °C		pH meter Meter ma	ike/model:	S/N		
			RESULTS					N RESULTS		Calibration Location:				
			S ) TIME					TIME		Electrode No.		Slope	Millivolts	
										Type: gel liquid	pH 7	Slope	Willivoits	
	KALINITY/ANC mg/L AS CaCO <sub>3</sub> ALKALINITY/ANC mg/L AS CaCO <sub>3</sub> other pH					pH								
			mg/L AS mg/L AS					mg/L AS H mg/L AS C		town all from before				
ACID:	ID: 1.6N 0.16N 0.01639N Acid: 1.6N 0.16N 0.01639N							1						
OTHER:									pH					
										Check				
									*******	pH				
		ERED C	IIIL HURN CONE		FILTERE	***************************************	rered Ch	ml HURN CONE		Comments/Calcula	tions:			
METHOD:		ON POINT	GRAN			INFLECTION		GRAN						
FIXED ENDPOINT					FIXED ENDPOINT									

MANUAL

STIRRING METHOD: MAGNETIC

STIRRING METHOD: MAGNETIC

MANUAL

GW Form version 8.0

FIELD ID	

## **QUALITY-CONTROL INFORMATION**

	PI	RESERVATIVE LOT NUMBER	<u>RS</u>			
7.5N — 7.7N HNO <sub>3</sub> Exp. Date: (METALS&CATIONS)	6N HCI Exp. Date (Hg)	4.5N H₂SO4 Exp. Date: (NUTRIENTS&DOC)	Conc. H₂SO4 Exp. Date: (COD, PHENOL, O&G)	1:1 HCl _ Exp. Date: (VOC)		
Pesticide (99202)		203)	 - -			
·	ameter codes require NWIS L	Filter Lot Numbers		was shim Dilitare hama		
Filter Type	Pore Size (microns)	Manufacturer's Lot Number	Parameter Code	NWIS Lot Number		
Capsule	0.45		99206			
Disc	0.45					
142 mm GFF (organics)	0.70					
25 mm GFF (organic carbon)	0.70					
142 mm membrane (inorganics)	0.45					
Starting date for set of samples (99109) (YMMDD) Ending date for set of samples (99110) (YMMDD) QC SAMPLES  Sample Type NWIS Record No. Sample Type NWIS Record No. Sample Type NWIS Record No. Equip Blank Sequential Trip Blank Other Split Concurrent Other Other Sequential Trip Blank Some Other Sequential Trip Blank Sequential Sequential Trip Blank						
99100 Blank-solution type  10 Inorganic grade (distilled/de 40 Pesticide grade (OK for org organic carbon) 50 Volatile-organic grade (OK organics, and organi 200 Other  99101 Source of blank water 10 NWQL 40 NIST 55 Wisconsin Mercury Lab	for VOCs, c carbon)  99102 Blank-samp 1 Source S 30 Trip 40 Sampler 50 Splitter 60 Filter 70 Preserval	olution	10 Topical for 20 Topical for 1	Fopical QC data (non-topical) nigh bias (contamination) ow bias (recovery)		
	1 No associated 10 Blank 30 Replicate Sam 40 Spike sample 100 More than one 200 Other  A complete set of		110 Topical for 120 Topical for 130 Topical for 140 Topical for 200 Topical for 900 Other topical	variability (field equip) variability (field collection) variability (field personnel) variability (field processing) variability (shipping&handling) variability (lab) al QC purpose		

7

#### REFERENCE LIST FOR CODES USED ON THIS FORM

A complete set of fixed-value codes can be found online at:

http://wwwnwis.er.usgs.gov/currentdocs/index.html

#### Sample Medium Codes

WG Regular Ground water WGQ Quality-control sample (Replicate or Spike) OAQ Blank

#### Value Qualifiers

- e see field comment
- f sample field preparation problem
- k counts outside the acceptable range

10	Routine
15	NAWQA
50	GW Network
110	Seepage Study
120	Irrigation Effects

Recharge

Injection

130

140

71999 Sample purpose

5	ampie Type Code
9	Regular
7	Replicate
2	Blank
1	Spike

Time Datum Codes								
	Std	UTC Dayligh						
	Time	Offset	Time	Offset				
Time Zone	Code	(hours)	Code	(hours)				
Hawaii-Aleutian	HST	-10	HDT	-9				
Alaska	AKST	-9	AKDT	-8				
Pacific	PST	-8	PDT	-7				
Mountain	MST	-7	MDT	-6				
Central	CST	-6	CDT	-5				
Eastern	EST	-5	EDT	-4				
Atlantic	AST	-4	ADT	-3				

#### Null-value Qualifiers

- e required equipment not functional or available
- f sample discarded; improper filter used
- o insufficient amount of water
- p sample discarded; improper preservation
- q sample discarded; holding time exceeded
- sample ruined in preparation

#### 50280 Purpose of site visit

2001 Primary (primary samples should not exist for a site for more than one date per HIP, and the primary sampling date generally has the highest number of NAWQA analytes)

2002 Supplemental (to fill in missing schedules not sampled or lost)

2003 Temporal characterization (for previously sampled schedules; includes LIP and seasonal samples)

2004 Resample (to verify questionable concentrations in primary sample)

2098 Ground-water quality control

2099 Other (ground-water related samples with medium code other than "6", such as soil samples or core material)

#### 82398 Sampling method

4010 Thief sampler 4020 Open-top bailer

4025 Double-valve bailer 4030 Suction pump

4040 Submersible pump

4045 Submersible multiple impeller (turbine) pump

Squeeze pump

4060 Gas reciprocating pump

4070 Gas lift

4080 Peristaltic pump

Jet pump 4090

4100 Flowing well

4110 Resin trap collector

8010 Other

#### 84164 Sampler type

Thief Sampler 4010 Open-top Bailer Double-valve Bailer 4025 4030 Suction Pump

Submersible Centrifugal Pump 4035 4040 Submersible Positive-pressure Pump

4041 Submersible Helical Rotor Pump 4045 Submersible Gear Pump 4050 Bladder Pump

Gas Reciprocating Pump 4060

4070 Gas Lift

4075 Submersible Piston Pump Peristaltic Pump

4080 4090 Jet pump

Line-Shaft Turbine Pump 4095

Flowing Well 4100

8010 Other

#### 72006 Sampling Condition

- 0.01 The site was dry (no water level is recorded)
- 0.02 The site had been flowing recently
- 0.03 The site was flowing, head could not be measured
- 0.04 A nearby site that taps the Aquifer was flowing
- 0.05 Nearby site tapping same Aquifer had been flowing recently
- 0.06 Injector site
- 0.07 Injector site monitor
- 0.08 Measurement discontinued
- 0.09 Obstruction encountered in well above water surface
- 0.10 The site was being pumped
- 0.11 The site had been pumped recently
- 0.12 Nearby site tapping the same Aquifer was being pumped
- 0.13 Nearby site tapping the Same Aquifer was pumped recently
- 0.14 Foreign substance present on the surface of the water
- 0.16 Water level affected by stage in nearby site 0.17 Other conditions affecting the measured water level
- 2 Undesignated
- 4 Flowing 6 Flowing on gas lift
- 23 Flowing to Pit 24 Water Flooding
- 25 Jetting 8 Pumping
- 10 Open hole
- 30 Seeping
- 18 Producing
- 31 Nearby well pumping 32 Nearby well taking water
- 19 Circulating 22 Lifting
- 33 Well taking water

#### Alkalinity/ANC Parameter Codes

39086 Alkalinity, water, filtered, incremental titration, mg/L

00418 Alkalinity, water, filtered, fixed endpoint, mg/L 29802 Alkalinity, water, filtered, Gran titration, mg/L

00419 ANC, water, unfiltered, incremental titration

00410 ANC, water, unfiltered, fixed endpoint, mg/L 29813 ANC, water, unfiltered, Gran titration, mg/L

29804 Bicarbonate, water, filtered, fixed endpoint, mg/L

63786 Bicarbonate, water, filtered, Gran, mg/L

00453 Bicarbonate, water, filtered, incremental, mg/L 00440 Bicarbonate, water, unfiltered, fixed endpoint, mg/L

00450 Bicarbonate, water, unfiltered, incremental, mg/L

29807 Carbonate, water, filtered, fixed endpoint, mg/L

63788 Carbonate, water, filtered, Gran, mg/L

00452 Carbonate, water, filtered, incremental, mg/L

00445 Carbonate, water, unfiltered, fixed endpoint, mg/L 00447 Carbonate, water, unfiltered, incremental, mg/L

29810 Hydroxide, water, filtered, fixed endpoint, mg/L

71834 Hydroxide, water, filtered, incremental, mg/L

71830 Hydroxide, water, unfiltered, fixed endpoint, mg/L

71832Hydroxide, water, unfiltered, incremental, mg/L

#### Dissolved Oxygen

AZIDE Azide-modified Winkler

INDIGO Sepctrophotometer, indigo carmine Field Kit, ndigo carmine, visual

INDKT LUMIN Luminscence sensor

8

MEMB2 Amperometric, Membrane (DODEC) Ampermetric, Membrand electrode MEMBR RHODA Field Kit, Rhodazine-D, visual SPC10 Spectrophotometer, Rhodazine-D

## 71875 Hydrogen Sulfide Odor

#### Value

# none entered (null)

Remark Code Method Code

M detect U un-acidified sample V acidified sample U non-detect

00003 Sampling depth, ft

78890 Sampling depth, ft blw msl

00059 Flow rate, instantaneous, gallons per minute

72004 Pump or flow period prior to sampling, minutes

#### Water Level

61055 Water level, depth below measuring point, feet

62610 Ground-water level above NGVD 1929, feet

62611 Ground-water level above NAVD 1988, feet

72019 Depth to water level, feet below land surface

Parameter and method codes for field measurements and turbidity can be found in separate attachments at http:// water.usgs.gov/usgs/owg/Forms.html

GW Form version 8.0

# U.S. GEOLOGICAL SURVEY – NATIONAL WATER QUALITY LABORATORY ANALYTICAL SERVICES REQUEST

THIS SECTION MANDATORY FOR SAMPLE LOGIN	
NWIS RECORD NUMBER  SAMPLE TRACKING ID  User Code  Project Account  NWQL LABOR	
STATION ID    2   0	mple Type
Science Center Contact Phone Number End Date (YYYYMMDD) End Time Science Center C	ontact Email
SITE / SAMPLE / SPECIAL PROJECT INFORMATION (Optional)	
State County SourceAgency Code Status* Analysis Source* Condition* Event* Custody	Sample Set
NWQL Proposal Number NWQL Contact Name NWQL Contact Email Pro	ogram/Project
Station Name: Field ID:	
Comments to NWQL:	
Hazard (please explain):  ANALYTICAL WORK REQUESTS: SCHEDULES AND LAB CODES (CIRCLE A=add D=dd SCHED 1: SCHED 2: SCHED 3: SCHED 4: SCHED 5: SCHED 5	
Lab Code:  A D Lab Code:	e: A D A D
Lab Code: A D Lab Code:	e: A D
SHIPPING INFORMATION (Number of containers sent)  ALF COD FA FU HUN RCB SAS BGC CU FAM FUS MBAS RU SUR C18 CUR FAR GCC RA RUR SUSO CC DIC FCA GCV RAM RURCV TBI CHL DOC FCC HFL RAR RUS TBY  NWQL Login Comments:	
Collected by: Phone No Date Shipped:	
FIELD VALUES  Lab/P Code Value Remark Lab/P Code Value Remark Lab/P Code 21/00095   51/00400   2/39086	_

\*MANDATORY FOR NWIS

Lab Use only

Form 9-3094 (August 2010)

# U.S. GEOLOGICAL SURVEY – ANALYTICAL SERVICES REQUEST (ASR) For USGS Contract No. 07CRCN0028 with TestAmerica Laboratories (TAL)

			SAMPL	E IDENTIFIC	ATION								
TAL RECORD		User Code		Project Acc	count						ONL' ORY		
	STATION	ID*	<b>2 0</b> Begin	<b>1</b> Date (YYYYM	MDD)*	Begin Tin	ne*	Me	edium	code		Sample	е Туре
USGS P	roject Cor	ntact Name	<b>2 0</b> End	<b>1</b> Date (YYYYMI	MDD)	End Tin	ne	US	GS F	roje	ct C	ontact	Emai
State Coun  Note: State, Coun  Lisa Uriel 303-736-01	ty, and Geo	Geologic A	Analysis Status a will not be	Analysis Source entered in by 0	Hydrolog Conditio	gic Hyd on E	rolog vent	3  ic	 30 da Tu	ırn A	JSG: .roun equir	S contr d Time ed	ract)
TAL Name & P		AL Contact Email	<u> </u>		USG	S Projec	t Nar	ne					
Station Name o	r Field ID:												
Sample conditi													
Analysis schedu	Note: Co	L WORK REQUE ntract Item Num								-	Vs)		
								Cor	ntaine	rs/Pr	esen	/atives	
CIN	Filtered (F) or Unfiltered (U)	Remarks: list ana and anion analyse					Unpres.	H2SO4	HN03	HCI	NaOH	ZnAc/ NaOH	
			CHAIN OF	CUSTODY	RECORD								
ASR: Relinquished by:				Date:				Т	ime:				
ASR: Received by:				Date:				Т	ime:				

USGS DODESP Contract ASR, revision 2.2, 01Oct2010